A VL real life claim example

Public & Products Liability

Service & Repair

The Insured operates a pleasure craft retail and service business in a remote South Island township. It was asked to service a 60HP outboard motor for a local company which ran river tours.

The Insured's servicemen re-assembled the engine but failed to replace the oil in the crank case. When it was being test-run the engine seized completely. As the engine was near new and beyond repair, the claim was settled by way of a replacement new motor under the Public Liability policy (Service and Repair Memorandum).

CEG 044-102019/000

